

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 27/07/2025

It is certified that the existing building **SUNRISE INTERNATIONAL SCHOOL** (name of the building or premises) at **Survey No. 115/2, Village-Mohi, Post- Bichhiya, Tehsil-Shamshabad, Distt. Vidisha (M.P.)** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor First Floor	-	-	-	-	-

The building is occupied by **SUNRISE INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on.....(date of inspection) in the presence of (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..... for a period ofyears in accordance with rule and subject to compliance of the specific conditions as appended.

1. The work has been completed to my best satisfaction.
2. The workmanship & all the materials have been used strictly in accordance with general and detailed satisfaction.
3. The building is structurally sound, safe and hygienic.
4. Hence it is fit for use how in with **SUNRISE INTERNATIONAL SCHOOL** is running.

Issued on at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : Vijay Kumar

Designation : Sub-engineer

Name & Address of Department/ Office: Shamshabad

उपसंज्ञी
नगर परिषद शामशाबाद

Annexure D

BUILDING SAFETY CERTIFICATE

Dated: 27/07/2025

No.

It is certified that the existing building **SUNRISE INTERNATIONAL SCHOOL** (name of the building or premises) at **Survey No. 115/2, Village-Mohi, Post- Bichhiya, Tehsil-Shamshabad, Distt. Vidisha (M.P.)** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground Floor First Floor	-	-	-	-	-

The building is occupied by **SUNRISE INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on.....(date of inspection) in the presence of (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..... for a period ofyears in accordance with rule and subject to compliance of the specific conditions as appended.

1. The work has been completed to my best satisfaction.
2. The workmanship & all the materials have been used strictly in accordance with general and detailed satisfaction.
3. The building is structurally sound, safe and hygienic.
4. Hence it is fit for use how in with **SUNRISE INTERNATIONAL SCHOOL** is running.

Issued on at.....by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name :

Designation :

Name & Address of Department/ Office:

उपयंत्री
नगर परिषद शामशाबाद